

Release Note

Release Date: 2008/2/20

Firmware Version:8.7.2.0-8.8.2.0

Utility Version:4280-4290

Rev	No.	Brand Name	Description	Date	Note
1	1		First Release(319 models)	2008/2/20	
2	1	HP	CLJ 2605	2008/9/17	new
	2	HP	CLJ CP1215		new
	3	HP	CLJ CP1518ni		new
	4	HP	CLJ CP3505dn		new
	5	HP	CM1015MFP		new
	6	HP	CM1017MFP		new
	7	HP	Deskjet 3940		new
	8	HP	LaserJet P2014		new
	9	HP	LaserJet P2015		new
	10	HP	OfficeJet J6480		new
	11	HP	OfficeJet Pro K5300		new
	12	HP	Photosmart C4480		new
	13	HP	Photosmart C4580		new
	14	HP	Photosmart D7260		new
	15	HP	PSC 2110		new
	16	HP	PSC 2310		new
	17	HP	PSC 2410		new
	18	HP	PSC 2510		new
	19	SAMSUNG	CLX-2160N		new
	20	SAMSUNG	ML-1610		new
	21	SAMSUNG	ML-2010(GDI)		new
	22	Lexmark	Z603		new
	23	Lexmark	Z645		new
	24	Epson	Aculaser C3800		new
	25	Epson	Stylus C59		new
	26	Epson	Stylus CX3700		new
	27	Epson	Stylus CX4900		new
	28	Epson	Stylus CX5505		new
	29	Epson	Stylus CX6900F		new
	30	Epson	Stylus TX200		new
	31	Konica Minolta	bizhub 200		new
	32	Kyocera	FS-1030D		new
	33	Kyocera	FS-1100		new
	34	Kyocera	FS-920		new

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
1	HP	Business 1000	OK	N/A		
2	HP	Business 1100d	OK	OK		
3	HP	Business 1200d	OK	OK		
4	HP	CLJ 1500L	OK	N/A		
5	HP	CLJ 1600	OK	N/A		
6	HP	CLJ 2550L	OK	--	OK	
7	HP	CLJ 2600n	OK	N/A	OK	
8	HP	CLJ 2605	OK	N/A	OK	Vista 64 not tested yet
9	HP	CLJ 3000dn	OK	N/A	OK	
10	HP	CLJ 3500	OK	N/A		
11	HP	CLJ 3500N	OK	N/A		
12	HP	CLJ 3600	OK	N/A		
13	HP	CLJ 3600dn	OK	N/A		
14	HP	CLJ 3600n	OK	N/A		
15	HP	CLJ 3700	OK	OK		
16	HP	CLJ 4600	OK	N/A		
17	HP	CLJ 5500	N/A	OK		
18	HP	CLJ 5500dn	N/A	OK		
19	HP	CLJ CP1215	NG	N/A	OK	
20	HP	CLJ CP1518ni	OK	N/A	OK	
21	HP	CLJ CP3505	OK	N/A	OK	
22	HP	CLJ CP3505dn	OK	N/A	OK	***
23	HP	CLJ3000dn	OK	N/A	OK	
24	HP	CM1015MFP	OK	N/A	OK	This model doesn't have Vista 64 driver
25	HP	CM1017MFP	OK	N/A	OK	This model doesn't have Vista 64 driver
26	HP	Deskjet 1120C	OK	N/A		
27	HP	Deskjet 1125C	N/A	OK		
28	HP	Deskjet 1180C	OK	OK		
29	HP	Deskjet 3325	OK	N/A		
30	HP	Deskjet 3535	OK	N/A		
31	HP	Deskjet 3550	OK	N/A		
32	HP	Deskjet 3650	OK	N/A		
33	HP	Deskjet 3820	OK	OK		
34	HP	Deskjet 3920	***OK	N/A		
35	HP	Deskjet 3940	OK	N/A	OK	
36	HP	Deskjet 450	OK	N/A		
37	HP	Deskjet 5160	OK	N/A		
38	HP	Deskjet 5440	OK	N/A		
39	HP	Deskjet 5550	OK	N/A		

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
40	HP	DeskJet 5652	OK	OK		
41	HP	DeskJet 5740	OK	N/A		
42	HP	Deskjet 6122	OK	OK		
43	HP	DeskJet 6540	OK	N/A		
44	HP	DeskJet 6840	OK	N/A		
45	HP	Deskjet 810C	OK	OK		
46	HP	DeskJet 845C	OK	N/A	OK	
47	HP	Deskjet 880C	OK	OK		
48	HP	Deskjet 882C	OK	OK		
49	HP	Deskjet 895cxi	OK	OK	OK	
50	HP	Deskjet 920C	OK	OK		
51	HP	Deskjet 9300	OK	OK		
52	HP	Deskjet 960	OK	N/A		
53	HP	Deskjet 9650	OK	OK		
54	HP	Deskjet 970cxi	OK	OK	OK	
55	HP	Deskjet 980	OK	N/A		
56	HP	Deskjet 990	OK	N/A		
57	HP	Deskjet 995C	OK	N/A		
58	HP	Deskjet D2360	OK	N/A		
59	HP	Deskjet D2460	OK	N/A	OK	
60	HP	Deskjet F2180	OK	N/A	OK	
61	HP	Deskjet F380	OK	N/A	OK	
62	HP	Deskjet F4185	OK	N/A	OK	OK
63	HP	DeskJet845C	OK	N/A	OK	
64	HP	LaserJet 1012	OK	N/A		
65	HP	LaserJet 1015	OK	N/A		
66	HP	LaserJet 1200	OK	OK		
67	HP	LaserJet 1220	OK	OK		
68	HP	LaserJet 1300	OK	OK		
69	HP	LaserJet 1320	OK	OK		
70	HP	LaserJet 2300	OK	N/A		
71	HP	LaserJet 2300L	OK	OK		
72	HP	LaserJet 2420	OK	OK		
73	HP	LaserJet 2420dn	OK	OK		
74	HP	LaserJet 2605	OK	N/A		
75	HP	LaserJet 2700	OK	N/A		
76	HP	LaserJet 3015	OK	OK		
77	HP	LaserJet 3020	OK	OK	OK	
78	HP	LaserJet 3030	OK	OK		

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
79	HP	LaserJet 3050	OK	N/A		
80	HP	LaserJet 3050z	OK	N/A	N/A	
81	HP	LaserJet 3052	OK	N/A		
82	HP	LaserJet 3055	OK	N/A		
83	HP	LaserJet 3200	OK	N/A		
84	HP	LaserJet 3300	OK	OK		
85	HP	LaserJet 3330mfp	OK	OK		
86	HP	LaserJet 3380	OK	OK	N/A	
87	HP	LaserJet 3390	OK	N/A		
88	HP	LaserJet 3392	OK	N/A		
89	HP	LaserJet 4200L	N/A	OK		
90	HP	LaserJet 4350	OK	OK		
91	HP	LaserJet 4650	OK	N/A		
92	HP	LaserJet 5100LE	N/A	OK		
93	HP	LaserJet 5100SE	N/A	OK		
94	HP	LaserJet 5200L	OK	OK		
95	HP	LaserJet 5200n	OK	OK	OK	
96	HP	LaserJet M1005MFP	OK	N/A	OK	
97	HP	LaserJet P2014	OK	N/A	OK	***
98	HP	LaserJet P2015	OK	N/A	OK	***
99	HP	OfficeJet 4110	OK	N/A		
100	HP	OfficeJet 4255	OK	N/A	OK	
101	HP	OfficeJet 4355	OK	N/A	OK	
102	HP	OfficeJet 5110	OK	OK		
103	HP	OfficeJet 5510	OK	N/A		
104	HP	OfficeJet 5610	OK	N/A	OK	
105	HP	OfficeJet 6110	OK	N/A		
106	HP	OfficeJet 6210	OK	N/A		
107	HP	OfficeJet 6310	OK	N/A	OK	
108	HP	OfficeJet 7130	OK	N/A		
109	HP	OfficeJet 7210	OK	N/A		
110	HP	OfficeJet 7410	OK	N/A	OK	
111	HP	OfficeJet 9100	OK	N/A		
112	HP	OfficeJet 9110	OK	OK		
113	HP	OfficeJet 9120	OK	OK		
114	HP	OfficeJet 9130	OK	OK		
115	HP	OfficeJet J5780	OK	N/A	OK	
116	HP	OfficeJet J6480	OK	N/A	OK	built in network function
117	HP	OfficeJet K7100	OK	--	OK	

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

***: Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
118	HP	OfficeJet K8600	OK	N/A	OK	
119	HP	OfficeJet Pro K5300	OK	N/A	OK	
120	HP	OfficeJet Pro K5400	OK	N/A		
121	HP	OfficeJet Pro K5400dn	OK	N/A	OK	
122	HP	OfficeJet Pro K550	OK	N/A	OK	
123	HP	OfficeJet Pro K850	OK	OK		
124	HP	OfficeJet Pro L7380	OK	N/A	OK	
125	HP	OfficeJet Pro L7580	Ok	N/A	OK	
126	HP	OfficeJet V40	OK	N/A		
127	HP	Photosmart 145	OK	N/A		
128	HP	Photosmart 245	OK	N/A		
129	HP	Photosmart 2575	OK	N/A	OK	
130	HP	Photosmart 2610	OK	N/A	OK	
131	HP	Photosmart 2710	OK	N/A		
132	HP	Photosmart 3110	OK	N/A		
133	HP	Photosmart 325	OK	N/A		
134	HP	Photosmart 3310	OK	N/A		
135	HP	Photosmart 375	OK	N/A		
136	HP	Photosmart 475	OK	N/A		
137	HP	Photosmart 7260	OK	N/A		
138	HP	Photosmart 7450	OK	N/A		
139	HP	Photosmart 7550	OK	N/A		
140	HP	Photosmart 7660	OK	N/A		
141	HP	Photosmart 7760	OK	N/A		
142	HP	Photosmart 7830	OK	N/A		
143	HP	Photosmart 7960	OK	N/A		
144	HP	Photosmart 8030	OK	N/A	OK	
145	HP	Photosmart 8230	OK	N/A	OK	
146	HP	Photosmart 8250	OK	N/A		
147	HP	Photosmart 8450	OK	N/A		
148	HP	Photosmart 8750	OK	N/A		
149	HP	Photosmart A526	OK	N/A	OK	
150	HP	Photosmart C3180	OK	N/A	OK	
151	HP	Photosmart C4180	OK	N/A		
152	HP	Photosmart C4280	OK	N/A	OK	
153	HP	Photosmart C4385	OK	N/A	OK	
154	HP	Photosmart C4480	OK	N/A	OK	no 2000 driver
155	HP	Photosmart C4580	OK	N/A	OK	no 2000 driver
156	HP	Photosmart C5180	OK	N/A	OK	

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
157	HP	Photosmart C6180	OK	N/A	OK	
158	HP	Photosmart C6280	OK	N/A	Ok	
159	HP	Photosmart C7180	Ok	N/A	OK	
160	HP	Photosmart C7280	OK	N/A	OK	
161	HP	Photosmart D5160	OK	N/A	OK	
162	HP	Photosmart D7160	OK	N/A		
163	HP	Photosmart D7260	OK	N/A	OK	built in network function
164	HP	Photosmart D7360	OK	N/A	OK	
165	HP	PSC 1110	OK	N/A		
166	HP	PSC 1210	OK	N/A	OK	
167	HP	PSC 1315	OK	N/A	OK	
168	HP	PSC 1350	OK	N/A		
169	HP	PSC 1410	OK	N/A	OK	
170	HP	PSC 1510	OK	N/A	OK	
171	HP	PSC 1610	OK	N/A	OK	
172	HP	PSC 2110	OK	N/A	OK	
173	HP	PSC 2210	OK	N/A		
174	HP	PSC 2310	OK	N/A	OK	
175	HP	PSC 2355	OK	N/A	OK	
176	HP	PSC 2410	OK	N/A	OK	
177	HP	PSC 2510	OK	N/A	OK	
178	HP	PSC 4110	OK	N/A		
179	HP	PSC 750	OK	N/A		
180	Canon	iC D380	OK	N/A		
181	Canon	S200SPx	OK	N/A		
182	Canon	C350	OK	N/A		
183	Canon	i255	OK	N/A		
184	Canon	i320	OK	N/A		
185	Canon	i355	OK	N/A		
186	Canon	i450	OK	N/A		
187	Canon	i455	OK	N/A		
188	Canon	i550	OK	N/A		
189	Canon	i850	OK	N/A		
190	Canon	i6100	OK	OK		
191	Canon	i6500	OK	OK		
192	Canon	i9100	OK	N/A		
193	Canon	i9950D	OK	N/A		
194	Canon	i475D	OK	N/A		
195	Canon	i560	OK	OK		

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
196	Canon	i865	OK	OK		
197	Canon	iR 2010	OK	OK		
198	Canon	iR 6000	N/A	OK		
199	Canon	iR 8500	N/A	OK		
200	Canon	iP90	OK	N/A		
201	Canon	iP1000	OK	N/A		
202	Canon	iP1200	OK	N/A	OK	
203	Canon	iP1880	OK	N/A	OK	
204	Canon	iP1500	OK	N/A		
205	Canon	iP2000	OK	N/A		
206	Canon	iP3000	OK	N/A		
207	Canon	iP3300	OK	N/A	OK	
208	Canon	iP3500	OK	N/A	OK	
209	Canon	iP4000	OK	OK		
210	Canon	iP4200	OK	N/A	OK	
211	Canon	iP4300	OK	N/A	OK	
212	Canon	iP4500	OK	N/A	OK	
213	Canon	iP5000	OK	N/A		
214	Canon	iP6000D	OK	N/A		
215	Canon	iP8500D	OK	N/A		
216	Canon	Pro 9000	OK	N/A		
217	Canon	iX4000	OK	N/A	OK	
218	Canon	iX5000	OK	N/A		
219	Canon	PIXMA MP110	OK	N/A		
220	Canon	PIXMA MP130	OK	N/A	OK	
221	Canon	PIXMA MP145	OK	N/A	OK	
222	Canon	PIXMA MP150	OK	N/A		
223	Canon	PIXMA MP160	OK	N/A		
224	Canon	PIXMA MP170	OK	N/A		
225	Canon	PIXMA MP180	OK	N/A		
226	Canon	PIXMA MP450	OK	N/A	OK	
227	Canon	PIXMA MP510	OK	N/A		
228	Canon	PIXMA MP520	OK	N/A	OK	
229	Canon	PIXMA MP700	OK	N/A		
230	Canon	PIXMA MP730	OK	N/A		
231	Canon	PIXMA MP780	OK	N/A		
232	Canon	Pro9000	OK	N/A	OK	
233	SAMSUNG	CLX-2160N	OK	N/A	OK	
234	SAMSUNG	ML-1520LP	OK	N/A		

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
235	SAMSUNG	ML-1610	OK	N/A	OK	
236	SAMSUNG	ML-1740	OK	OK		
237	SAMSUNG	ML-2010(GDI)	OK	N/A	OK	
238	SAMSUNG	SCX-4100	OK	OK		
239	SAMSUNG	SCX-4200	OK	OK		
240	SAMSUNG	SCX-4521F	OK	OK	OK	
241	SAMSUNG	SCX-4720F	OK	OK		
242	SAMSUNG	SF-565P	OK	OK	OK	
243	Lexmark	P4350	OK	N/A	--	No Vista
244	Lexmark	X6170	OK	N/A	OK(Vista 64)	No Vista32
245	Lexmark	Z1420	OK	N/A	OK	
246	Lexmark	Z603	OK	N/A	OK	**
247	Lexmark	Z615	OK	N/A		**
248	Lexmark	Z645	OK	N/A	OK	**
249	Lexmark	Z705	OK	N/A		**
250	Lexmark	Z810	OK	N/A		**
251	Lexmark	Z816	OK	N/A		**
252	Lexmark	Z818	OK	N/A	OK(Vista 32)	**No Vista 64
253	Lexmark	E120	OK	N/A		
254	Lexmark	E230	OK	OK		
255	Lexmark	C510	OK	OK		
256	Epson	Aculaser C1900	OK	OK		
257	Epson	Aculaser C4000	OK	OK		
258	Epson	Aculaser C3800	OK	OK	OK	
259	Epson	Aculaser C4100	OK	OK		
260	Epson	Aculaser C8600	OK	OK		
261	Epson	DLQ-3500C	OK	OK		
262	Epson	EPL-5900L	OK	OK	OK(Vista32)	***No Vista 64
263	Epson	EPL-6100	OK	OK		
264	Epson	EPL-6200	OK	OK	OK(Vista32)	No Vista 64
265	Epson	EPL-N2500	OK	OK		
266	Epson	EPL-N2750	N/A	OK		
267	Epson	EPL-N3000	OK	OK		
268	Epson	LQ-300+	N/A	OK		
269	Epson	LQ-300+II	OK	N/A	OK(Vista32)	No Vista64
270	Epson	LQ-680C	N/A	OK		
271	Epson	LQ-2080C	N/A	OK		
272	Epson	PictureMate	OK	N/A		
273	Epson	Stylus C43UX	OK	N/A		

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

***: Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
274	Epson	Stylus C45	OK	N/A	OK	
275	Epson	Stylus C59	OK	N/A	OK(Vista32)	no Vista64
276	Epson	Stylus C63	OK	N/A		
277	Epson	Stylus C67	OK	N/A		
278	Epson	Stylus C83	OK	N/A		
279	Epson	Stylus C88	OK	N/A		
280	Epson	Stylus C90	OK	N/A	OK	
281	Epson	Stylus C110	OK	N/A	OK	
282	Epson	Stylus C4100	OK	N/A	OK	
283	Epson	Stylus COLOR 740	OK	OK	OK	
284	Epson	Stylus COLOR 880	OK	Not Test		
285	Epson	Stylus COLOR 900	OK	Not Test		
286	Epson	Stylus COLOR 1160	OK	N/A		
287	Epson	Stylus CX1500	OK	N/A		
288	Epson	Stylus CX3100	OK	N/A		
289	Epson	Stylus CX3700	OK	N/A	OK	
290	Epson	Stylus CX3900	OK	N/A	OK	
291	Epson	Stylus CX4100	OK	N/A	OK	
292	Epson	Stylus CX4700	OK	N/A	OK	
293	Epson	Stylus CX4900	OK	N/A	OK	
294	Epson	Stylus CX5100	OK	N/A		
295	Epson	Stylus CX5300	OK	N/A		
296	Epson	Stylus CX5500	OK	N/A	OK	
297	Epson	Stylus CX5505	OK	N/A	OK	
298	Epson	Stylus CX5700F	OK	N/A		
299	Epson	Stylus CX5900	OK	N/A	OK	
300	Epson	Stylus CX6900F	OK	N/A	OK	
301	Epson	Stylus CX7300	OK	N/A	OK	
302	Epson	Stylus CX8300	OK	N/A	OK	
303	Epson	Stylus CX9300F	OK	N/A	OK	
304	Epson	Stylus CX9400F	OK	N/A	OK	
305	Epson	Stylus TX200	OK	N/A	OK	
306	Epson	Stylus PHOTO750	OK	OK	OK	
307	Epson	Stylus PHOTO 830U	OK	N/A		
308	Epson	Stylus PHOTO 935	OK	N/A		
309	Epson	Stylus PHOTO 1390	OK	N/A	OK	
310	Epson	Stylus PHOTO 2100	OK	OK		
311	Epson	Stylus PHOTO R210	OK	N/A		

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
312	Epson	Stylus PHOTO R230	OK	N/A		
313	Epson	Stylus PHOTO R270	OK	N/A	--	
314	Epson	Stylus PHOTO R340	OK	N/A		
315	Epson	Stylus PHOTO R350	OK	N/A		
316	Epson	Stylus PHOTO RX430	OK	N/A		
317	Epson	Stylus PHOTO RX510	OK	N/A		
318	Epson	Stylus PHOTO RX520	OK	N/A		
319	Epson	Stylus PHOTO RX530	OK	N/A	OK	
320	Epson	Stylus PHOTO RX590	OK	N/A	OK	
321	Epson	Stylus PHOTO RX630	OK	N/A		
322	Epson	Stylus PHOTO RX650	OK	N/A	OK	
323	Brother	HL-2070	OK	N/A		
324	Brother	HL-5240	OK	N/A		
325	Brother	MFC-210C	OK	N/A		
326	Brother	MFC-215C	OK	N/A		
327	Brother	MFC-2820	OK	N/A		
328	Brother	MFC-3240C	OK	N/A		
329	Brother	MFC-420CN	OK	N/A		
330	Brother	MFC-425CN	OK	N/A		
331	Brother	MFC-4800J	OK	N/A		
332	Brother	MFC-7420	OK	N/A		
333	Brother	MFC-7820N	OK	N/A		
334	Brother	MFC-8840D	OK	N/A		
335	Konica Minolta	Magicolor 2480MF	OK	N/A	OK(Vista 32)	***No Vista64
336	Konica Minolta	Magicolor 5550	OK	N/A		
337	Konica Minolta	Magicolor 5570	OK	N/A		
338	Konica Minolta	bizhub 200	OK	N/A	OK(Vista 32)	No Vista64
339	Kyocera	FS-1030D	OK	OK	OK	
340	Kyocera	FS-1100	OK	N/A	OK	
341	Kyocera	FS-920	OK	OK	OK	
342	Dell	944	OK	N/A		
343	Dell	Mono LaserMFP1125	OK	N/A		*** No Win2000

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.