


4-Pair Termination Tool Guide


1

Available options


1. DN-93615/DN-93604
2. DN-93616



Button









Guide slot




Tool body

2

1. Insert the guide slot of die into the tool.
2. Press the button at both sides and fix the die securely.
3. Move forward the die and make sure it's completely fixed.



3



Install the wires, and place them securely into the insulation displacement terminals following the appropriate color code.
(T568A or T568B)